

BRACKETT AERO FILTERS, INC.



<u>INSTRUCTIONS</u>

ASSEMBLY PART NO. BA-5110A

APPROVED ON AIRCRAFT MODELS: SEE FAA APPROVED APPLICABILITY LIST

REPLACES: P/N C294510-0301 or P/N 12615

FAA APPROVAL DATA: STC-SA71GL List No. 1

FAA-PMA Supplement No. 1

Your new polyurethane air filter element has been designed to provide maximum dust collecting efficiency, non-restrictive air flow, and economical element replacement, while maintaining a lightweight filter. The element has been treated with a distinctive treatment called a wetted agent and is approximately 98% efficient. The wetted agent is an accompaniment in the efficient capturing of dust. In addition, the element has received a fire retardant treatment. For the above reasons, replace the element each 100 hours of use/12 months or when 50% covered with foreign material. DO NOT WASH AND REUSE

INSTALLATION INSTRUCTIONS

- STEP 1. Remove original air filter and discard.
- STEP 2. Install filter assembly onto aircraft using the same procedure as original.
- NOTE: It is very important that the filter frame be securely fastened. If any fastener or receptacle is broken or bad, either replace or bolt frame in place, making sure of gasket compression.
- STEP 3. Remove element BA-6108 from plastic bag. Install into frame assembly, making sure the taper of the element matches the taper of the frame and that is made on all sides.
- STEP 4. Fasten grill onto frame with the 2 ea. AN526-832R6 screws and lockwashers, placing the grill against the foam.
- STEP 5. NOTE: After initial installation of filter assembly, fill out FAA Form 337 for return to service. On future replacement of parts this form will not be required.
- SERVICING: Under normal conditions, replace filter element, PN BA-6108, after 100 hours use or 1 year intervals. Under severely dusty conditions, <u>check daily</u> and replace when element is 50% covered with foreign material. For Continued Airworthiness see I-194 Document.

Instruction Sheet Part No. 5111 Date Rev: 04-02-04 Mfg. by: BRACKETT AERO FILTERS, INC. Kingman, AZ

United States Of America

Bepartment of Transportation - Federal Abiation Administration

Supplemental Type Certificate

Number SA71GL

This Certificate issued to

BRACKETT AERO FILTERS, INC.

7052 Government Way Kingman, Arizona 86401

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part * of the * Regulations.

Original Product Type Certificate Number: * *See attached Approved Model List (AML)

Make:

*(AML) No. SA71GL for list of approved aircraft

Model:

*models and applicable airworthiness regulations.

Description of Type Design Change: Installation of air filters in accordance with AML No. SA71GL dated April 17, 1995, or later FAA approved revision.

Similations and Conditions. Approval of this change in type design applies to the above aircraft model(s) only. This approval should not be extended to aircraft of this model on which other previously approved modifications are incorporated unless it is determined that the interrelationship between this change and any of those other previously approved modifications will introduce no adverse effect upon the airworthiness of that aircraft. A copy of this Certificate and FAA Approved Model List (AML) No. SA71GL dated April 17, 1995, or later FAA approved revision must be maintained as part of the permanent records for the modified aircraft.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: January 9, 1975

Date reissued: March 3, 1983, June 20, 2000

Date of issuance : February 21, 1975

Date amended : April 17, 1995

By direction of the Administrator

Manager, Tech. and Admin. Support Staff Los Angeles Aircraft Certification Office

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both

FAA APPROVED MODEL LIST (AML) NO. SA71GL BRACKETT AERO FILTERS, INC.

FOR INSTALLING AIR FILTERS

														_		
Issue Date: April 17, 1995	AML	AMENDMENT DATE	7/12/95	7/12/95	7/12/95	7/12/95		7/12/95	7/12/95				-			
ıe Date: 🗡		CERT. BASIS	CAR3	CAR 3	CAR3	CAR 10		CAR3	CAR 10		FAR 23		FAR 23	FAR 23	FAR 23	
nssl	ORIGINAL TYPE	CERTIFICATE NUMBER	A-799	3A12	A-803	A4EU	OF DATA ***	3A12	A4EU	OF [A34CE	OF DATA ***	A13CE	A20CE	A26EU	OF DATA
		AIRCRAFT MODEL	170/A/B	172/A/B/C/D/E/F/G/H/I/K/L/M	M-18C	(Cessna) F172D/E/F/G/H/K/L/M	*** END	172N, P	(Cessna) F172N, P	QNB ***	T303	END ***	177/A/B	177RG	(Cessna) F177RG	*** END
		AIRCRAFT MAKE	Cessna	Cessna	Mooney Mite	Reims Aviation		Cessna	Reims Aviation		Cessna		Cessna	Cessna	Reims Aviation	
)P VING	REVISION & DATE	H 5/5/95				D 5/5/95			N/C 7/22/88		C 6/3/86				
	TOP DRAWING	NUMBER	~			BA-5110			BA-5110A			BA-5210				BA-5710
	AIR FILTER	FILTER MODEL NUMBER BA-5110			BA-5110A			BA-5210		BA-5710						
		ITEM 34			35			36		37						

BRACKETT AIR FILTER DOCUMENT I-194

PLACE IN AIRCRAFT RECORDS

CONTINUED AIRWORTHINESS INSPECTION REQUIREMENTS AS PER FAR 23.1529 AND GENERAL PROCEDURES OF PART 43

INSPECTION INTERVALS: Pre-flight inspections, engine backfire inspection, 100 hour inspections, annual inspections, filter element replacements.

INSPECTION PROCEDURES

- A. Pre-flight inspection: Per Pilots Operating Handbook, check filter assembly for security, damage or 50% contamination of element face. If found report to maintenance personnel prior to flight.
- B. Engine start-up backfire inspection: Prior to flight, check the entire intake system for security or damage. If a fire was present, the downstream face of the foam element will show erosion. If any irregularities are found see Chart I and also refer to the Aircraft Maintenance Manual for the intake system.
- C. At element replacement intervals: With the element removed, inspect the filter grill, filter frame, filter mountings and entire intake system for security, wear and any deformation. Note: On filter assemblies with gaskets, visually inspect inside and outside of frame for any signs of gasket looseness, movement or deterioration. If found refer to Chart I or the proper maintenance manual for your aircraft or component.

PART	RED	REILACE	INSTRUCTIONS
FRAME	Χ		COMPLETE NEW ASSEMBLY
GASKET	X		ON FILTER FRAME, REMOVE OLD NEOPRENE GASKET AND ALL TRACES OF ADHESIVE DOWN TO A CLEAN ANODIZED FRAME SURFACE. USE ADHESIVE 3M#847 OR DOW CORNING RTV-732. COAT ENTIRE MATING SURFACE (GASKET TO FRAME). APPLY ADHESIVE FOLLOWING MANUFACTURER'S LABEL DIRECTIONS. WHEN FRAME AND GASKET ARE PLACED TOGETHER, CLAMP OR WEIGHT DOWN AT .75 LB./SQ. IN. OF CONTACT AREA. ALLOW TO CURE 24 HOURS PRIOR TO INSTALLATION. PRIOR TO REINSTALLATION OF FILTER, CHECK AIRBOX MATING SURFACE FOR IRREGULARITIES. IF FOUND, CORRECT PER MANUFACTURER'S REQUIREMENTS. UPON REINSTALLATION CHECK THAT THE GASKET MAKES 100% CONTACT. THE GASKET SHOULD BE COMPRESSED 50% FOR OPTIMUM SEAL.
GRILL	Χ		REPLACE WITH NEW GRILL
HARDWARE	Χ		REPLACE UNSERVICEABLE WITH NEW
SCREEN	Χ		COMPLETE NEW ASSEMBLY
SCREEN/GASKET	Χ		COMPLETE NEW ASSEMBLY (ASSEMBLIES USING SCREEN GASKETS PRE 1981; BA-4106, BA-5110 AND BA-8110.)
ELEMENT	X		REPLACE ELEMENT

DATE: 3-16-94 CHART 1