

BRACKETT AERO FILTERS, INC.



# **INSTRUCTIONS**

## ASSEMBLY PART NO. BA-7310

APPROVED ON AIRCRAFT MODELS: SEE FAA APPROVED APPLICABILITY LIST.

FAA APPROVAL DATA: STC-SA71GL LIST NO. 1 FAA-PMA SUPPLEMENT NO. 1

Your new polyurethane air filter element has been designed to provide maximum dust collecting efficiency, non-restrictive air flow, and economical element replacement, while maintaining a lightweight filter. The element has been treated with a distinctive treatment called a wetted agent and is approximately 98% efficient. The wetted agent is an accompaniment in the efficient capturing of dust. In addition, the element has received a fire retardant treatment. For the above reasons, replace the element each 200 hours of use, 12 months or when 50% covered with foreign material. DO NOT WASH AND REUSE.

## INSTALLATION INSTRUCTIONS

- STEP 1. Remove Beech cowl grill.
- STEP 2. Remove and discard original filter.
- STEP 3. Install replacement filter frame PN BA-7300. NOTE: Due to the soft neoprene gasket it will require firm pressure on your screw driver to compress the gasket and lock the studs. The frame is now permanently mounted.
- STEP 4. Install element, PN BA-7305, first blot off excessive wettant, then push into frame, making sure you have made good contact with the frame on all sides.
- STEP 5. Install grill, PN BA-7301, with the 2 ea. 8-32 screws and lock washers. Place the smooth side of the grill screw tabs facing forward, so the grill makes contact with the element.
- STEP 6. For future element replacements remove the grill only and replace element PN BA-7305.
- STEP 7. Replace Beech cowling cover.
- STEP 8. NOTE: After initial installation of filter assembly, fill out FAA form 337 for return to service. On future replacement of parts this form will not be required.
- SERVICING: Under normal conditions, replace filter element, P.N. BA-7305, after 200 hours use or1 year intervals. Under severely dusty conditions, <u>check daily</u> and replace when element is 50% covered with foreign material. For Continued Airworthiness Instructions, see Form I-194.

Instruction Sheet Part No. BA-7306 Date Rev: 07-20-04 Mfg. by: BRACKETT AERO FILTERS, INC. Kingman, AZ FAA APPROVED MODEL LIST (AML) NO. SA71GL BRACKETT AERO FILTERS, INC. FOR INSTALLING AIR FILTERS Issue Date: April 17, 1995

			r		Т				T			]
	AML	AMENDMENT DATE	10/30/97				10/30/97					
		CERT. BASIS	CAR 3	*	CAR 3	3A15   :ND OF DATA ***	CAR 3	ND OF DATA ***	CAR 3		CAR 3	
ORIGINAL	ТҮРЕ	CERTIFICATE NUMBER	A777		3A15		A1CE		3A16	95-55, 95-A55, 95-B55 3A16 *** END OF DATA ***	3A16	*** END OF DATA ***
		AIRCRAFT MODEL	35, A35, B35 (SN D-2201 thru D-2605)		S35 (SN D-7310 thru D-7671)		C23, A24R, B24R, C24R, B19		95-55, 95-A55, 95-B55		E55, E55A (SN TE-1079 and UP), 58, 58A (SN TH-741 and UP)	
		AIRCRAFT MAKE	Beech		Beech		Beech		Beech		Beech	
	VING	REVISION & DATE		C 4/15/96		C 12/30/81		C 4/12/96		B 11/29/81	N/C 12/7/82	
	DRAV	NUMBER	BA-7310			BA-7410		BA-7510		BA-7610	BA-7710	
AIR	AIR FILTER MODEL NUMBER			BA-7310		BA-7410		BA-7510		BA-7610	BA-7710	
	ITEM			46		47		48		49	20	

United States Of America Bepartment of Transportation - Federal Abiation Administration



Number SATIGL

This Certificate issued to

BRACKETT AERO FILTERS, INC. 7052 Government Way Kingman, Arizona 86401

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part \* of the \* Regulations.

 Original Deduct Type Certificate Number : \* \*See attached Approved Model List (AML)

 Make :
 \*(AML) No. SA71GL for list of approved aircraft

 Model :
 \*models and applicable airworthiness regulations.

Description of Type Design Change: Installation of air filters in accordance with AML No. SA71GL dated April 17, 1995, or later FAA approved revision.

*Bimitations and Conditions.* Approval of this change in type design applies to the above aircraft model(s) only. This approval should not be extended to aircraft of this model on which other previously approved modifications are incorporated unless it is determined that the interrelationship between this change and any of those other previously approved modifications will introduce no adverse effect upon the airworthiness of that aircraft. A copy of this Certificate and FAA Approved Model List (AML) No. SA71GL dated April 17, 1995, or later FAA approved revision must be maintained as part of the permanent records for the modified aircraft.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application. January 9, 1975

Date of issuance February 21, 1975



Date reissued March 3, 1983, June 20, 2000

Date amended . April 17, 1995

By direction of the Administrator

Hm Liza Mal

Manager, Tech. and Admin. Support Staff Los Angeles Aircraft Certification Office (Tule)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both

This certificate may be transferred in accordance with FAR 21.47.



BRACKETT AIR FILTER DOCUMENT I-194

### PLACE IN AIRCRAFT RECORDS

#### CONTINUED AIRWORTHINESS INSPECTION REQUIREMENTS AS PER FAR 23.1529 AND GENERAL PROCEDURES OF PART 43

INSPECTION INTERVALS: Pre-flight inspections, engine backfire inspection, 100 hour inspections, annual inspections, filter element replacements.

### INSPECTION PROCEDURES

- A. Pre-flight inspection: Per Pilots Operating Handbook, check filter assembly for security, damage or 50% contamination of element face. If found report to maintenance personnel prior to flight.
- B. Engine start-up backfire inspection: Prior to flight, check the entire intake system for security or damage. If a fire was present, the downstream face of the foam element will show erosion. If any irregularities are found see Chart I and also refer to the Aircraft Maintenance Manual for the intake system.
- C. At element replacement intervals: With the element removed, inspect the filter grill, filter frame, filter mountings and entire intake system for security, wear and any deformation. Note: On filter assemblies with gaskets, visually inspect inside and outside of frame for any signs of gasket looseness, movement or deterioration. If found refer to Chart I or the proper maintenance manual for your aircraft or component.

PART	RED.	INSTRUCTIONS
FRAME	Х	COMPLETE NEW ASSEMBLY
GASKET	X	ON FILTER FRAME, REMOVE OLD NEOPRENE GASKET AND ALL TRACES OF ADHESIVE         DOWN TO A CLEAN ANODIZED FRAME SURFACE.         USE ADHESIVE 3M#847 OR DOW CORNING RTV-732. COAT ENTIRE MATING         SURFACE (GASKET TO FRAME). APPLY ADHESIVE FOLLOWING MANUFACTURER'S         LABEL DIRECTIONS. WHEN FRAME AND GASKET ARE PLACED TOGETHER,         CLAMP OR WEIGHT DOWN AT .75 LB./SQ. IN. OF CONTACT AREA. ALLOW TO         CURE 24 HOURS PRIOR TO INSTALLATION.         PRIOR TO REINSTALLATION OF FILTER, CHECK AIRBOX MATING SURFACE FOR         IRREGULARITIES. IF FOUND, CORRECT PER MANUFACTURER'S REQUIREMENTS.         UPON REINSTALLATION CHECK THAT THE GASKET MAKES 100% CONTACT. THE         GASKET SHOULD BE COMPRESSED 50% FOR OPTIMUM SEAL.
GRILL	Х	REPLACE WITH NEW GRILL
HARDWARE	Х	REPLACE UNSERVICEABLE WITH NEW
SCREEN	Х	COMPLETE NEW ASSEMBLY
SCREEN/GASKET	Х	COMPLETE NEW ASSEMBLY ( ASSEMBLIES USING SCREEN GASKETS ) PRE 1981; BA-4106, BA-5110 AND BA-8110. )
ELEMENT	Х	REPLACE ELEMENT